

Installation Guide Errata – 05/02/02

Raptor ATX Motherboard Installation Guide – Revision 04 – P/N MN-RBXAX-04

- Page 6 - *Table I-6* – The watchdog timeout option 150 ms is not available. The reset signal lasts 250ms. Therefore, the watchdog cannot have the option of 150ms. The same applies to *Table D-2* on page 60.
- Page 59 & 43– The time out range 150 milliseconds should be disregarded.