

BIOS history GA-BX2000

BIOS Version (Date)	Description
F9 (Jan. 14, 2002)	1. Fixed : The computer will not resume from standby (ACPI S1) mode by PS/2 mouse or keyboard
F8 (Nov.27, 2001)	1. Fix disable temperature alarm failed ! 2. Added press power button can shutdown when into S1
F7 (Jul 11, 2000)	1. Support Celeron 533A to 700 CPU(FC-PGA). (PCB revision : 1.1 or above) 2. Fixed 533A CPU show 533
F6 (Jul 06, 2000)	1. Support the following EEPROM: a. WINBOND 49F002U b. HYUNDAI 29F002TC c. AMIC A29002L d. ST M29F002BT2
F5 (Jun 21, 2000)	1. Fixed Celeron 533 show Celeron-MMX 533 2. Fixed system beep when boot up from WIN98 ACPI mode
F4 (May 29, 2000)	1. Fixed some CPU Clock display incorrect
F3 (May 10, 2000)	1. Support MX29F002NTQC-12 Flash Rom in Dual BIOS Utility 2. Support Slot 1 CPUID 683h Micro Code 0Ch 3. Support PPGA CPUID 683h Micro Code 10h 4. Fix FC-PGA Celeron CPU will show Pentium III
F2 (Dec.21, 1999)	1. Combined GA-MG400 VGA BIOS "G400-15.BIN".
F1 (Oct.27, 1999)	1. Replace the display string of "-5V:" to "-5V:-".
1.8 (Sep.15, 1999)	1. Support Coppermine CPU. (PCB revision : 1.1 or above) 2. Support IBM 35G HDD. 3. Solve Promise Ultra DMA66 RAID CARD STR failure Problem. 4. Solve Samsung SFD-012 FDD QAPLUS stress test failure problem.
1.7 (Aug.02, 1999)	1. Support update DMI/ESCD/BOTH in the SETUP menu. 2. Patch Intel82558/82559 3COM LAN card PME function abnormally in APM/ACPI mode. 3. Update some DMI information. 4. Fix the IBM 15.2G HDD size capture error in FDISK.exe
1.6 (Jul.01, 1999)	1. Add New CPU Patch Code (CPUID=673, PATCH ID=28/05).
1.5 (Jun.22, 1999)	1. Solve Windows 2000 build 2024 installation failure 2. Solve SST 39020 EEPROM unknown flash type problem
1.4 (May.04, 1999)	1. Changes DualBIOS algorithm to protect against CIH and other BIOS-attacking viruses.
1.3 (Apr.02, 1999)	1. Fix "wrong fan speed"
1.1 (Mar.09, 1999)	1. Support DualBIOS spec. 0.1d. 2. Support Dual Color LED.
1.0 (Feb.23, 1999)	1. Initial release.