

BIOS Revision History

Bios name	Remarks
FS56S20D	Checksum: 6F00 Initial release Date: 2004/04/20
FS56S20I	Checksum: EF00 Date: 2004/07/20 1. Improve DDR compatibility. 2. Added Celeron D CPU microcode. 3. Patch detect IDE devices too slow.
FS56S20L	Checksum: 3D00 Date: 2004/09/06 1. Support E-Stepping CPU. 2. Fixed system unstable issue when install Prescott CPU with WindowsXP SP2.
FS56S20T	Checksum: FA00 Date: 2004/09/24 1. Fixed Prescott Celeron D 2.4G unstable.
FS56S20V	Checksum: 0A00 Date: 2004/10/18 1. Improve DDR compatibility.
FS56S20Z	Checksum: 5500 Date: 2004/11/04 1. Patch P4 FSB800 2.4G CPU can't enter OS. 2. Patch system can't boot when plug USB device. 3. Patch can't resume from S3 after loading optimized.
FS56S210	Checksum: 9500 Date: 2004/12/10 1. Patch HW monitor fail with Prescott CPU.
FS56S212	Checksum: E400 Date: 2005/02/25 1. Patch Northwood Celeron CPU can't enter OS.
FS56S213	Checksum: 5900 Data: 2005/03/16 1. Patch USB keyboard function fail.
FS56S214	Checksum: 2300 Data: 2005/05/16 1. Patch Kreton DDR400 unstable.

Close this window