

Affected products

The following products are supported by this BIOS release.

Product	Variant
GL815E	GL815E-FPL, GL815E-L
SC815E	SC815E-FPL, SC815E-L, SC815E-FPA
CH815C	CH815C-2L
EPC2225/2325	EPC2225(S), EPC2325(S)
Hopwood, Hopwood 2	No variants

Compatible baseboard data

The table lists the baseboard data part numbers required for full functionality by this release.

Product	Part Number	Product	Part Number	Product	Part Number
GL815E-FPL	97-4112-07	SC815E-FPA	97-4283-00	Hopwood	97-4146-01
GL815E-L	97-4113-06	CH815C-2L	97-4186-02	Hopwood 2	97-4401-01
SC815E-FPL	97-4115-06	EPC2225/2325	97-4178-05		
SC815E-L	97-4116-04	Staple Hill	97-4199-03		

Note

After updating the BIOS, the contents of the CMOS RAM are lost and the board must be reconfigured. Any custom defaults that have been saved to the flash ROM must also be recreated.

Changes for this release

The following changes from the previous release have been incorporated into this release. Listed changes to support new products do not imply support for those products with this BIOS release - see the Affected Products section for a list of supported products.

BIOS Change from Release 2.03.10 to 2.03.11			Track No.
Item	Description of Change	Reason for Change	
1.	Modifications to force the minimum RTC date to 01-01-2001.	WinXP requirement	
2.	Fixed RadiSys CSR (CMOS Save and Restore). <i>SETUP, EXIT, CMOS Restore Condition</i> will always reflect the Restore Condition saved in FLASH. If the CSR in FLASH is erased, the <i>CMOS Restore Condition</i> is set to <i>Never</i> .	Ensure consistency of BIOS settings.	
3.	Modified <i>SETUP, Version Information, PLD Software</i> display to support 3-5-4 P/N.	Provide support for both the new 3-5-4 and old 2-4-2 P/N formats.	

RadiSys is a trademark of RadiSys Corporation
All other trademarks, registered trademarks, service marks and trade names are the property of their respective owners.
Copyright © RadiSys Technology (Ireland) Limited, July 2004. All rights reserved.

Changes to baseboard data

There are no changes to product baseboard data with this release.

Changes to update disks

There are no changes to the update disk software with this release.

Limitations of this release

Limitations and known problems with this release are described in the product limitations document.