**Driver Version:** 5.00
**Published:** Oct 21, 2009

These release notes include important information about D-Link LAN adapter driver revisions. Please verify that these release notes are correct for your adapter:

- If you are installing a new LAN adapter, please check the hardware version on the device label; make sure that your adapter meets the system requirement of this driver version. Please refer to

- Revision History and System Requirement for detailed driver and hardware matrix.

- Please install the drivers before inserting LAN adapter into the computer's PCI/PCIe slot.

For more detailed information regarding our LAN adapter products, please refer to Related Documentation.

You can also download the LAN adapter drivers from http://tsd.dlink.com.tw.

**Content:**

## Revision History and System Requirement:

| Driver Version | Date | Model | Hardware Version |
|---|---|---|---|
| V5.00 | 21-Oct-09 | DFE-528TX | E2/E1 |
| V4.00 | 01-Nov-06 | DFE-528TX | E2/E1 |
| V3.00 | 12-Aug-06 | DFE-528TX | E2/E1 |
| V2.00 | 01-Jan-06 | DFE-528TX | E2/E1 |
|  |  |  |  |

## New Features:

| Driver Version | New Features |
|---|---|
| V5.00 | **Support the following Operating Systems:**<br>Windows 7 x86/x64 (WHQL passed): v. 6.111.723.2009<br>Windows Server 2008 x86/x64 (WHQL passed): v. 6.101.1124.2006 |
| V4.00 | **Support the following Operating Systems:**<br>Microsoft Vista x86: v. 6.101.1124.2006<br>Microsoft Vista x64: v. 6.101.1124.2006<br>Netware Server 3.12/4.1X/5.00: v. 3.29<br>Netware DOS ODI Client: v. 3.61<br>Microsoft Windows 95 / 98 / ME: v. 5.392.1229.2000 / v. 5.397.823.2001 / v. 5.397.823.2001<br>Microsoft Windows NT4.0: v. 5.392.1229.2000<br>Microsoft Windows 2000/2003: v. 5.397.823.2001 / v. 5.503.326.2002<br>Microsoft Windows XP: v. 5.503.326.2002<br>Linux : kernel v2.2.x: v. 1.11a<br>Apple Mac 10.1 or new: v.3.00<br>DOS NDIS Driver: v. 3.23<br>Microsoft Network client 3.0 for MS-DOS: v. 3.23<br>Microsoft LAN Manager Workstation/Server: v. 3.23<br>Packet Driver: v. 3.21<br>SCO Unix 5.0: v. 5.0.0 |
| V3.00 | 1. **Phase in latest D-Link Autorun format**<br>2. **Support the following Operating Systems:**<br>Netware Server 3.12/4.1X/5.00: v. 3.29<br>Netware DOS ODI Client: v. 3.61<br>Microsoft Windows 95 / 98 / ME: v. 5.392.1229.2000 / v. 5.397.823.2001 / v. 5.397.823.2001<br>Microsoft Windows NT4.0: v. 5.392.1229.2000<br>Microsoft Windows 2000/2003: v. 5.397.823.2001 / v. 5.503.326.2002<br>Microsoft Windows XP: v. 5.503.326.2002<br>Linux : kernel v2.2.x: v. 1.11a<br>Apple Mac 10.1 or new: v.3.00<br>DOS NDIS Driver: v. 3.23<br>Microsoft Network client 3.0 for MS-DOS: v. 3.23 |

| | |
|---|---|
| | Microsoft LAN Manager Workstation/Server: v. 3.23<br>Packet Driver: v. 3.21<br>SCO Unix 5.0: v. 5.0.0<br>Diagnostic Utility: V1.1.5.2 |
| V2.00 | **Support the following Operating Systems:**<br>Netware Server 3.12/4.1X/5.00: v. 3.29<br>Netware DOS ODI Client: v. 3.61<br>Microsoft Windows 95 / 98 / ME: v. 5.392.1229.2000 / v. 5.397.823.2001 / v. 5.397.823.2001<br>Microsoft Windows NT4.0: v. 5.392.1229.2000<br>Microsoft Windows 2000/2003: v. 5.397.823.2001 / v. 5.503.326.2002<br>Microsoft Windows XP: v. 5.503.326.2002<br>Linux : kernel v2.2.x: v. 1.11a<br>Apple Mac 10.1 or new: v.3.00<br>DOS NDIS Driver: v. 3.23<br>Microsoft Network client 3.0 for MS-DOS: v. 3.23<br>Microsoft LAN Manager Workstation/Server: v. 3.23<br>Packet Driver: v. 3.21<br>SCO Unix 5.0: v. 5.0.0 |
| | |

## Problem Fixed:

| Driver Version | Problems Fixed |
|---|---|
| V5.00 | N/A |
| V4.00 | N/A |
| V3.00 | N/A |
| V2.00 | N/A |

\* D-Link tracking number is enclosed in ()

## Known Issues:

| Driver Version | Problems Fixed |
|---|---|
| V5.00 | N/A |

| V4.00 | N/A |
|-------|-----|
| V3.00 | N/A |
| V2.00 | N/A |
|       |     |

## Related Documentation:

- DFE-528TX Quick Installation Guide