

NEED HELP?

 [Email Us](#)

 [Find service locations](#)

The following table shows the supported CPUs for this motherboard [Click here to search other motherboards.](#)

| CPU | Validated since PCB | Validated since BIOS | Note |
|---|---------------------|----------------------------|------|
| Xeon 5020(2.50GHz 667FSB,2X2MB L2,C1) | 1.03G | 1009 GO | |
| Xeon 5030(2.66GHz 667 FSB,2X2MB L2,C1) | 1.03G | 1009 GO | |
| Xeon 5040(2.83GHz 667FSB,2X2MB L2,C1) | 1.03G | 1009 GO | |
| Xeon 5050(3.00GHz 667FSB,2 X 2MB L2,C1) | 1.03G | 1009 GO | |
| Xeon 5060(3.20GHz,1066FSB,2X2MB L2,C1) | 1.03G | 1009 GO | |
| Xeon 5063(3.20GHz 1066FSB,2X2MB L2,C1) | 1.03G | 1009 GO | |
| Xeon 5070(3.46GHz 1066FSB,2X2MB L2,C1) | 1.03G | 1009 GO | |
| Xeon 5080(3.73GHz 1066FSB,2X2MB L2,C1) | 1.03G | 1009 GO | |
| Xeon 5110(1.60GHz 1066FSB,4MB L2,B2) | 1.03G | 1009 GO | |
| Xeon 5110(1.60GHz 1066FSB,4MB L2,G0) | 1.03G | 1009 GO | |
| Xeon 5120(1.86 GHz 1066FSB,4MB L2,G0) | 1.03G | 1009 | |

| | | | |
|---|-------|------|--------------------|
| | | | GO |
| Xeon 5120(1.86GHz 1066FSB,4MB L2,B2) | 1.03G | 1009 | GO |
| Xeon(5130) 2.00 GHz(1333 MHz FSB/4MB L2, B2) | 1.03G | 1009 | GO |
| Xeon(5130) 2.00 GHz(1333 MHz FSB/4MB L2, G0) | 1.03G | 1009 | GO |
| Xeon(5140) 2.33 GHz(1333 MHz FSB/4MB L2, B2) | 1.03G | 1009 | GO |
| Xeon(5140) 2.33 GHz(1333 MHz FSB/4MB L2, G0) | 1.03G | 1009 | GO |
| Xeon(5150) 2.66 GHz(1333 MHz FSB/4MB L2, B2) | 1.03G | 1009 | GO |
| Xeon(5150) 2.66 GHz(1333 MHz FSB/4MB L2, G0) | 1.03G | 1009 | GO |
| Xeon(5160) 3.00 GHz(1333 MHz FSB/4MB L2, B2) | 1.03G | 1009 | GO |
| Xeon(5160) 3.00 GHz(1333 MHz FSB/4MB L2, G0) | 1.03G | 1009 | GO |
| Xeon(E5205) 1.86 GHz(1066 MHz FSB/6MB L2, C0) | 1.03G | 1009 | GO |
| Xeon(E5205) 1.86 GHz(1066 MHz FSB/6MB L2, E0) | 1.03G | 1009 | GO |

| | | |
|---|-------|------------|
| Xeon(E5310) 1.60 GHz(1066 MHz FSB/8MB L2, B3) | 1.03G | 1009 GO |
| Xeon(E5310) 1.60 GHz(1066 MHz FSB/8MB L2, G0) | 1.03G | 1009 GO |
| Xeon(E5320) 1.86 GHz(1066 MHz FSB/8MB L2, B3) | 1.03G | 1009 GO |
| Xeon(E5320) 1.86 GHz(1066 MHz FSB/8MB L2, G0) | 1.03G | 1009 GO |
| Xeon(E5335) 2.00 GHz(1333 MHz FSB/8MB L2, B3) | 1.03G | 1009 GO |
| Xeon(E5335) 2.00 GHz(1333 MHz FSB/8MB L2, G0) | 1.03G | 1009 GO |
| Xeon(E5345) 2.33 GHz(1333 MHz FSB/8MB L2, B3) | 1.03G | 1009 GO |
| Xeon(E5345) 2.33 GHz(1333 MHz FSB/8MB L2, G0) | 1.03G | 1009 GO |
| Xeon(E5405) 2.00 GHz(1333 MHz FSB/12MB,C0) | 1.03G | 1009 GO |
| Xeon(E5405) 2.00 GHz(1333 MHz FSB/12MB,E0) | 1.03G | 1009 GO |
| Xeon(E5410) 2.33 GHz(1333 MHz FSB/12MB,C0) | 1.03G | 1009 GO |
| Xeon(E5410) 2.33 GHz(1333 MHz FSB/12MB,E0) | 1.03G | 1009 GO |

| | | |
|---|-------|------------|
| Xeon(E5420) 2.50 GHz(1333 MHz FSB/12MB,C0) | 1.03G | 1009 GO |
| Xeon(E5420) 2.50 GHz(1333 MHz FSB/12MB,E0) | 1.03G | 1009 GO |
| Xeon(E5430) 2.66 GHz(1333 MHz FSB/12MB,C0) | 1.03G | 1009 GO |
| Xeon(E5430) 2.66 GHz(1333 MHz FSB/12MB,E0) | 1.03G | 1009 GO |
| Xeon(E5440) 2.83 GHz(1333 MHz FSB/12MB,E0) | 1.03G | 1009 GO |
| Xeon(E5440) 2.83 GHz(1333 MHz FSB/12MB,C0) | 1.03G | 1009 GO |
| Xeon(E5450) 3.00 GHz(1333 MHz FSB/12MB,C0) | 1.03G | 1009 GO |
| Xeon(E5450) 3.00 GHz(1333 MHz FSB/12MB,E0) | 1.03G | 1009 GO |
| Xeon(L5240) 3.00 GHz(1333 MHz FSB/6MB L2,E0) | 1.03G | 1009 GO |
| Xeon(L5310) 1.60 GHz(1066 MHz FSB/8MB L2, B3) | 1.03G | 1009 GO |
| Xeon(L5310) 1.60 GHz(1066 MHz FSB/8MB L2, GO) | 1.03G | 1009 GO |
| Xeon(L5320) 1.86GHz(1066 MHz FSB/8MB L2, B3) | 1.03G | 1009 GO |

| | | |
|--|-------|------------|
| Xeon(L5320) 1.86GHz(1066 MHz FSB/8MB L2, G0) | 1.03G | 1009 GO |
| Xeon(L5335) 2.00GHz(1333 MHz FSB/8MB L2, G0) | 1.03G | 1009 GO |
| Xeon(L5410) 2.33GHz(1333 MHz FSB/12MB L2, C0) | 1.03G | 1009 GO |
| Xeon(L5410) 2.33GHz(1333 MHz FSB/12MB L2, E0) | 1.03G | 1009 GO |
| Xeon(L5420) 2.50GHz(1333 MHz FSB/12MB L2,C0) | 1.03G | 1009 GO |
| Xeon(L5420) 2.50GHz(1333 MHz FSB/12MB L2,E0) | 1.03G | 1009 GO |
| Xeon(L5430) 2.66GHz(1333 MHz FSB/12MB L2,E0) | 1.03G | 1009 GO |
| Xeon(LV L5240) 3.00 GHz(1333 MHz FSB/6MB L2,C0) | 1.03G | 1009 GO |
| Xeon(LV5148) 2.33 GHz(1333 MHz FSB/4MB L2, B2) | 1.03G | 1009 GO |
| Xeon(LV5148) 2.33 GHz(1333 MHz FSB/4MB L2, G0) | 1.03G | 1009 GO |
| Xeon(X5260) 3.33 GHz(1333 MHz FSB/6MB L2, C0) | 1.03G | 1009 GO |
| Xeon(X5260) 3.33 GHz(1333 MHz FSB/6MB L2, E0) | 1.03G | 1009 GO |

| | | | |
|--|-------|------|--------------------|
| Xeon(X5270) 3.50 GHz(1333 MHz FSB/6 MB L2, E0) | 1.03G | 1009 | GO |
| Xeon(X5355) 2.66 GHz(1333 MHz FSB/8 MB L2, B3) | 1.03G | 1009 | GO |
| Xeon(X5355) 2.66 GHz(1333 MHz FSB/8 MB L2, G0) | 1.03G | 1009 | GO |
| Xeon(X5365) 3.00 GHz(1333 MHz FSB/8 MB L2, G0) | 1.03G | 1009 | GO |
| Xeon(X5450) 3.00 GHz(1333 MHz FSB/12 MB L2, C0) | 1.03G | 1009 | GO |
| Xeon(X5450) 3.00 GHz(1333 MHz FSB/12 MB L2, E0) | 1.03G | 1009 | GO |
| Xeon(X5460) 3.16 GHz(1333 MHz FSB/12 MB L2, C0) | 1.03G | 1009 | GO |
| Xeon(X5460) 3.16 GHz(1333 MHz FSB/12 MB L2, E0) | 1.03G | 1009 | GO |
| Xeon(X5470) 3.33 GHz(1333 MHz FSB/12 MB L2, E0) | 1.03G | 1009 | GO |

Shop and Learn

Mobile

Phones

Accessories

Laptops

Workstations

Accessories

**Motherboards /
Components**

Wired Networking

Intelligent Robots

AIoT & Industrial Solutions

Servers

Learn More

Asus Design Center

ASUSPRO

Automotive Solutions

AVC Licensing Notice

Support

Check Repair Status

Find Service Locations

Product Registration

Email Us