

# BIOS Revision History

Bios name	Remarks
FB61RS01	Checksum: 7301 Date: 08/25/2003 Initial release.
FB61RS05	Checksum: 6D4A Date: 09/24/2003 1. Fixed Maxtor S-ATA HDD problem when bios set Raid mode. 2. Set 'Drive A' default is "None" in BIOS setup menu. 3. Set 'First Boot Device' default is "CDROM" in BIOS setup menu. 4. Set 'Third Boot Device' default is "LS120" in BIOS setup menu. 5. Set 'Boot Up Floppy Seek' default is "Disabled" in BIOS setup menu.
FB61RS06	Checksum: 6300 Date: 11/17/2003 1. Support P4 Extreme Edition(P4EE) CPU. 2. Add P-BIOS function on FSB 800MHz if Turbo mode set 'Enable' 3. Set S-ATA default as 'Auto' 4. Support IDE DMA transfer access in DOS mode.
FB61RS08	Checksum: 8B00 Date: 02/25/2004 Update raid bios to 3.5.4.3003
FB61RS0A	Checksum: B700 Date: 05/14/2004 1. Change sign on message to "Shuttle 20 Year Special Edition". 2. Update CPU microcode.
FB61RS0C	Checksum: 2900 Date: 08/23/2004 1. Fix CPU Vcore adjustment function. 2. Fix Matrox G550 compatibility issue.

Close this window