

BIOS Revision History

Bios name	Remarks
FS40S022	Date code: 04/30/2002 Initial release.
FS40S030	Date code: 07/05/2002 checksum: 9400h 1. Fix under S1, CPU fan won't stop issue. 2. Add boot from lan function. 3. Change cpu fan controller from fan1 to fan3 as default. 4. Fan controller default is enable.
FS40S032	Date code: 08/12/2002 checksum: 1E00 1. Fixed Duron 1.2G will showed Athlon 1.2G
FS40S037	Date code: 09/11/2002 checksum: 6F00 1. Support ATHLON XP CPU 2400+, 2600+. 2. Added USB devices booting function. 3. Added bioslock function. 4. Added the new fan speed table 5. Added CPU frequency item '133/166/33' and '166/166/33' which support 166 Mhz cpu. (for over clock function)
FS40S039	Date code: 12/23/2002 checksum: 2000 1. Fixed 2400+ showing error
FS40S042	Date code: 01/21/2003 checksum: FC00 1. Support 'Power Fail Resume' function 2. Fixed it show 'Printer Port' under WIN2000
FS40S043	Date code: 08/19/03 checksum: 2C00 1. Added Thorton CPU support code.
FS40S045	Date: 12/12/2003 Checksum : D900 1. Support Duron 1.3G Palomino CPU

Close this window