

# BIOS Revision History

Bios name	Remarks
FS51SB0C	Date:12/17/2002 Checksum:5B00 Initial release.
FS51SB0F	Date:05/30/2003 Checksum:FC00 1. Update microcode for Northwood Package 2. Set DRAM Addr/Cmd rate default with 2T
FS51SB0K	Date:11/17/2003 Checksum:8900 1. Add fan 'Ultra Low,Low,Middle,High speed' function and no diskette in USB Zip system hang keyboard default as 'Enabled' 2. Fixed only plug usb keyboard & cardreader 3. Set usb
FS51SB0L	Date:12/02/2003 Checksum:A900 Fixed system unstable issue, while installing DDR 256MB+512MB together.

Close this window