











## NEED HELP?

 [Email Us](#)

 [Find service locations](#)

The following table shows the supported CPUs for this motherboard [Click here to search other motherboards.](#)

CPU	Validated since PCB	Validated since BIOS	Note
Xeon 5020(2.50GHz 667FSB,2X2MB L2,C1)	1.02G	1008 	
Xeon 5030(2.66GHz 667 FSB,2X2MB L2,C1)	1.02G	1008 	
Xeon 5040(2.83GHz 667FSB,2X2MB L2,C1)	1.02G	1008 	
Xeon 5050(3.00GHz 667FSB,2 X 2MB L2,C1)	1.02G	1008 	
Xeon 5060(3.20GHz,1066FSB,2X2MB L2,C1)	1.02G	1008 	
Xeon 5063(3.20GHz 1066FSB,2X2MB L2,C1)	1.02G	1008 	
Xeon 5070(3.46GHz 1066FSB,2X2MB L2,C1)	1.02G	1008 	
Xeon 5080(3.73GHz 1066FSB,2X2MB L2,C1)	1.02G	1008 	
Xeon 5110(1.60GHz 1066FSB,4MB L2,B2)	1.02G	1008 	
Xeon 5110(1.60GHz 1066FSB,4MB L2,G0)	1.02G	1008 	
Xeon 5120(1.86 GHz 1066FSB,4MB L2,G0)	1.02G	1008	

			<a href="#">GO</a>
Xeon 5120(1.86GHz 1066FSB,4MB L2,B2)	1.02G	1008	<a href="#">GO</a>
Xeon(5130) 2.00 GHz(1333 MHz FSB/4MB L2, B2)	1.02G	1008	<a href="#">GO</a>
Xeon(5130) 2.00 GHz(1333 MHz FSB/4MB L2, G0)	1.02G	1008	<a href="#">GO</a>
Xeon(5140) 2.33 GHz(1333 MHz FSB/4MB L2, B2)	1.02G	1008	<a href="#">GO</a>
Xeon(5140) 2.33 GHz(1333 MHz FSB/4MB L2, G0)	1.02G	1008	<a href="#">GO</a>
Xeon(5150) 2.66 GHz(1333 MHz FSB/4MB L2, B2)	1.02G	1008	<a href="#">GO</a>
Xeon(5150) 2.66 GHz(1333 MHz FSB/4MB L2, G0)	1.02G	1008	<a href="#">GO</a>
Xeon(5160) 3.00 GHz(1333 MHz FSB/4MB L2, B2)	1.02G	1008	<a href="#">GO</a>
Xeon(5160) 3.00 GHz(1333 MHz FSB/4MB L2, G0)	1.02G	1008	<a href="#">GO</a>
Xeon(E5205) 1.86 GHz(1066 MHz FSB/6MB L2, C0)	1.02G	1008	<a href="#">GO</a>
Xeon(E5205) 1.86 GHz(1066 MHz FSB/6MB L2, E0)	1.02G	1008	<a href="#">GO</a>

Xeon(E5310) 1.60 GHz(1066 MHz FSB/8MB L2, B3)	1.02G	1008 GO
Xeon(E5310) 1.60 GHz(1066 MHz FSB/8MB L2, G0)	1.02G	1008 GO
Xeon(E5320) 1.86 GHz(1066 MHz FSB/8MB L2, B3)	1.02G	1008 GO
Xeon(E5320) 1.86 GHz(1066 MHz FSB/8MB L2, G0)	1.02G	1008 GO
Xeon(E5335) 2.00 GHz(1333 MHz FSB/8MB L2, B3)	1.02G	1008 GO
Xeon(E5335) 2.00 GHz(1333 MHz FSB/8MB L2, G0)	1.02G	1008 GO
Xeon(E5345) 2.33 GHz(1333 MHz FSB/8MB L2, B3)	1.02G	1008 GO
Xeon(E5345) 2.33 GHz(1333 MHz FSB/8MB L2, G0)	1.02G	1008 GO
Xeon(E5405) 2.00 GHz(1333 MHz FSB/12MB,C0)	1.02G	1008 GO
Xeon(E5405) 2.00 GHz(1333 MHz FSB/12MB,E0)	1.02G	1008 GO
Xeon(E5410) 2.33 GHz(1333 MHz FSB/12MB,C0)	1.02G	1008 GO
Xeon(E5410) 2.33 GHz(1333 MHz FSB/12MB,E0)	1.02G	1008 GO

Xeon(E5420) 2.50 GHz(1333 MHz FSB/12MB,C0)	1.02G	1008 GO
Xeon(E5420) 2.50 GHz(1333 MHz FSB/12MB,E0)	1.02G	1008 GO
Xeon(E5430) 2.66 GHz(1333 MHz FSB/12MB,C0)	1.02G	1008 GO
Xeon(E5430) 2.66 GHz(1333 MHz FSB/12MB,E0)	1.02G	1008 GO
Xeon(E5440) 2.83 GHz(1333 MHz FSB/12MB,E0)	1.02G	1008 GO
Xeon(E5440) 2.83 GHz(1333 MHz FSB/12MB,C0)	1.02G	1008 GO
Xeon(E5450) 3.00 GHz(1333 MHz FSB/12MB,C0)	1.02G	1008 GO
Xeon(E5450) 3.00 GHz(1333 MHz FSB/12MB,E0)	1.02G	1008 GO
Xeon(E5462) 2.80 GHz(1600 MHz FSB/12MB,C0 )	1.02G	1008 GO
Xeon(E5462) 2.80 GHz(1600 MHz FSB/12MB,E0 )	1.02G	1008 GO
Xeon(E5472) 3.00 GHz(1600 MHz FSB/12MB ,C0)	1.02G	1008 GO
Xeon(E5472) 3.00 GHz(1600 MHz FSB/12MB,E0 )	1.02G	1008 GO

Xeon(L5240) 3.00 GHz(1333 MHz FSB/6MB L2,E0 )	1.02G	1008 GO
Xeon(L5310) 1.60 GHz(1066 MHz FSB/8MB L2, B3)	1.02G	1008 GO
Xeon(L5310) 1.60 GHz(1066 MHz FSB/8MB L2, G0)	1.02G	1008 GO
Xeon(L5320) 1.86GHz(1066 MHz FSB/8MB L2, B3)	1.02G	1008 GO
Xeon(L5320) 1.86GHz(1066 MHz FSB/8MB L2, G0)	1.02G	1008 GO
Xeon(L5335) 2.00GHz(1333 MHz FSB/8MB L2, G0)	1.02G	1008 GO
Xeon(L5410) 2.33GHz(1333 MHz FSB/12MB L2, CO)	1.02G	1008 GO
Xeon(L5410) 2.33GHz(1333 MHz FSB/12MB L2, EO)	1.02G	1008 GO
Xeon(L5420) 2.50GHz(1333 MHz FSB/12MB L2,CO)	1.02G	1008 GO
Xeon(L5420) 2.50GHz(1333 MHz FSB/12MB L2,E0)	1.02G	1008 GO
Xeon(L5430) 2.66GHz(1333 MHz FSB/12MB L2,E0)	1.02G	1008 GO
Xeon(LV L5240) 3.00 GHz(1333 MHz FSB/6MB L2,CO )	1.02G	1008 GO

Xeon(LV5148) 2.33 GHz(1333 MHz FSB/4MB L2, B2)	1.02G	1008 GO
Xeon(LV5148) 2.33 GHz(1333 MHz FSB/4MB L2, G0)	1.02G	1008 GO
Xeon(X5260) 3.33 GHz(1333 MHz FSB/6MB L2, C0)	1.02G	1008 GO
Xeon(X5260) 3.33 GHz(1333 MHz FSB/6MB L2, E0)	1.02G	1008 GO
Xeon(X5270) 3.50 GHz(1333 MHz FSB/6MB L2, E0)	1.02G	1008 GO
Xeon(X5272) 3.40 GHz(1600 MHz FSB/6MB L2, C0)	1.02G	1008 GO
Xeon(X5272) 3.40 GHz(1600 MHz FSB/6MB L2,E0)	1.02G	1008 GO
Xeon(X5355) 2.66 GHz(1333 MHz FSB/8MB L2, B3)	1.02G	1008 GO
Xeon(X5355) 2.66 GHz(1333 MHz FSB/8MB L2, G0)	1.02G	1008 GO
Xeon(X5365) 3.00 GHz(1333 MHz FSB/8MB L2, G0)	1.02G	1008 GO
Xeon(X5450) 3.00 GHz(1333 MHz FSB/12MB L2,C0)	1.02G	1008 GO
Xeon(X5450) 3.00 GHz(1333 MHz FSB/12MB L2,E0)	1.02G	1008 GO

Xeon(X5460) 3.16 GHz(1333 MHz FSB/12MB L2,C0)	1.02G	1008 <a href="#">GO</a>
Xeon(X5460) 3.16 GHz(1333 MHz FSB/12MB L2,E0)	1.02G	1008 <a href="#">GO</a>
Xeon(X5470) 3.33 GHz(1333 MHz FSB/12MB L2,E0 )	1.02G	1008 <a href="#">GO</a>
Xeon(X5472) 3.00 GHz(1600 MHz FSB/12MB,E0 )	1.02G	1008 <a href="#">GO</a>
Xeon(X5472) 3.00 GHz(1600 MHz FSB/6MB,C0 )	1.02G	1008 <a href="#">GO</a>
Xeon(X5482) 3.20 GHz(1600 MHz FSB/12MB L2, E0)	1.02G	1008 <a href="#">GO</a>
Xeon(X5492) 3.40 GHz(1600 MHz FSB/12MB L2, E0)	1.02G	1008 <a href="#">GO</a>

### Shop and Learn

- Mobile
  - Workstations
- Phones
  - Accessories
- Accessories
  - Motherboards / Components**
  - Motherboards
  - Graphics Cards
  - Gaming Cases
  - Cooling
  - Power Supply Units
- Laptops
  - For Home
  - For Work
  - For Creators
  - For Students

### Learn More

- Asus Design Center
- ASUSPRO
- Automotive Solutions
- AVC Licensing Notice
- ASUS Blog

- Wired Networking
- Intelligent Robots
- AIoT & Industrial Solutions
- Servers
- Smart Home
- Accessories**
- Keyboards
- Mice and Mouse Pads

### Support

- Check Repair Status
- Find Service Locations
- Product Registration
- Email Us
- Call Us
- Security Advisory
- ASUS Support Videos
- MyASUS